4540 West Stone Drive Suite B Kingsport, Tn
Phone: 423-230-0752 Fax 423-245-1858
E-mail: robtcb4fibercom@embarqmail.com or fibercom@chartertn.net
"Organization is listed by the American Industrial Hygiene Association (AIHA) in the Asbestos Analysts Registry Program"

FiberCom Laboratory, Inc. Analytical Request & Report

Sample for: ASBESTOS ID's (PLM)

Date Received: 6/15/09
Date Reported: 6/15/09

Location: Vacant Bldg.-16745 Lincoln Street-Kingsport, Tn

Submitter: John Doe
Project # 01-9999-05

Analytical Results

Sample ID Client/Lab		Sample Location	Description	Result	% Asbestos
1	09999-1	Locker Room	Wall Plaster	ND	
2	09999-2	Locker Room	Wall Plaster	ND	
3	09999-3	Locker Room	Ceiling Plaster	ND	
4	09999-4	Locker Room	Plaster Ceiling	ND	
5	09999-5	Locker Room	9x9 FT Red	Chrysotile	3% Both
6	09999-6	Freezer Area	Sprayed Ceiling	Chrysotile	15%
7	09999-7	Not Provided	9x9 FT White w/ Mastic	Chrysotile	3% Both
8	09999-8	Bathroom	9x9 FT Cream	Chrysotile	3% Tile
9	09999-9	TV Room	Window Glazing	ND	
10	09999-10	TV Room	9x9 FT Gray	Chrysotile	3%
11	09999-11	TV Room	Wall Plaster w/ Sheetrock	ND	

Sample

QC Blank: Fiberglass

ANALYTICAL METHOD: NIOSH 9002 Issue 2 8/15/94 or EPA 600/R-93/116 PLM

Analyst: Buddy Bellamy FC request No. FIBL09999 DATE: 6/15/09

ND=None Detected (Asbestos Not Present in Representative Sample).The results pertain only to the sample identification above. The sample may not be fully representative of the larger material in question.The condition of the sample analyzed was acceptable upon receipt unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, ect. was provided by the client. This report shall not be reproduced, except in full, without consent of FiberCom Laboratory, Inc.